

Single Ended Data Input Swing	V_{IN}	mVp-p	350		800
Transmit Disable Voltage	V_{DIS}	V	2		3.5
Transmit Enable Voltage	V_{EN}	V	-0.3		0.8
Transmit Fault Assert Voltage	V_{FA}	V	2		3.5
Transmit Fault De-Assert Voltage	V_{FDA}	V	-0.3		0.8
Receiver					
Single Ended Data Output Swing	V_{OD}	mVp-p	185		900
LOS Fault	V_{LOSFT}	V	2		3.5
LOS Normal	V_{LOSNR}	V	-0.3		0.8